February 8, 2008

Dear Sirs:

Name of Company:BELLUNA CO., LTD.Code No.: 99971st Section of the Tokyo Stock Exchange

Notice of Additional Targets for Voluntary Recall and Free Replacement

On February 5, 2008, Belluna Co., Ltd. announced that regarding Neo Universal Electric Beds and other beds in the same series, it has found the remote control developed a fault, the concerns about safety on designing of the remote control, and the strong folding force of the mattress. Following the discovery, the Company will voluntarily recall the beds. However, reviewing the scope of the targets, the Company should add the following products within the scope, and also will voluntarily recall these beds and replace them with modified products free of charge.

The Company regrets any inconvenience its actions cause customers, and kindly asks for their understanding and cooperation.

Description

1. Scope of Recall and Replacement / Measures to Prevent a Recurrence

Based on the results of the causal investigation, the Company placed the following products within the scope of its voluntary recall and free product replacement, to ensure product safety and to free customers from any anxiety. The Company will take these preventive measures to assure safety.

Commodity name	Туре	Units sold	Sales launch	Sales termination		
Additional Products						
Universal MAX	Single	243	April 2007	January 2008		
	Reduced-size double	56	April 2007	January 2008		
	Sub total	299				
Universal MAX2	Single	346	July 2007	December 2007		
	Reduced-size double	96	July 2007	December 2007		
	Sub total	442				
Electric Bed United	Single	105	March 2005	August 2007		
	Reduced-size double	31	March 2005	August 2007		
	Sub total	136				

(1) Products subject to the voluntary recall and free replacement

Disclaimer: This is an English translation of the captioned release. This translation is prepared and provided for the purpose of the reader's convenience. All readers are recommended to refer to the original version in Japanese of the release for complete information.

Commodity name	Туре	Units sold	Sales launch	Sales termination		
The Best Buy Electric Reclining Bed	Single	1,579	November 2006	January 2008		
	Reduced-size double	186	November 2006	January 2008		
	Sub total	1,765				
Electric Bed with a futon and a table	Single	325	July 2007	January 2008		
	Reduced-size double	103	July 2007	January 2008		
	Sub total	428				
Electric Bed Louis Garcia	Single	143	April 2006	July 2007		
	Sub total	143				
Louis Garcia Electric Reclining Bed	Single	677	April 2007	January 2008		
	Reduced-size double	206	April 2007	January 2008		
	Sub total	883				
Total		4,096				
Conference: Scope as of February 5, 2008						
Neo Universal	Single	6,667	April 2005	May 2006		
	Reduced-size double	1,624	April 2005	May 2006		
	Double (*)	736	April 2005	May 2006		
	Sub total	9,027				
Universal 5	Single	10,723	December 2005	December 2006		
	Reduced-size double	2,601	December 2005	November 2006		
	Sub total	13,324				
Universal DX	Single	100	July 2006	July 2006		
	Reduced-size double	16	July 2006	July 2006		
	Sub total	116				
Universal 6	Single	1,418	November 2006	October 2007		
	Reduced-size double	334	November 2006	October 2007		
	Sub total	1,752				
Universal 7	Single	328	September 2007	January 2008		
	Reduced-size double	71	September 2007	January 2008		
	Sub total	399				
Total		24,618				
Inclusive Total		28,714				

(*: The accident involved this type.)

(2) Delivery of the notice, to alert customers and inform them of the voluntary recall and free replacement (began on February 6, 2008)

[Notification methods]

- 1. Direct mail, telephone call, facsimile transmission and e-mail, etc.
- 2. Announcement at the Company's website

(3) Improvement methods

[Remote control]

- 1. Installation of a master electrical switch
- 2. Adoption of concave remote control buttons (Remote controls for existing models have convex buttons.)
- 3. Strengthening of remote control buttons
- 4. Waterproofing
- 5. Affixing of a warning sticker

[Main bed unit]

- 1. Installation of a driving mechanism that prevents the motor from applying excessive force when a user has a hand or head caught between frames
- 2. Installation of safety mesh (in the frame section)
- 3. Affixing of a warning sticker

(4) Replacement method

The Company will replace the remote control and the drive units currently used with safer counterparts, and install a safety mesh.

(5) Replacement period

Middle of March 2008 onwards (schedule)

- END -